
IDFG Angler Access Update





- Notified by anglers in late summer that water was low
- Determined headgate leakage was cause
- Inflow < Outflow

















